

Change of motor
Reset of "service-alarm"
RONDA – Version 2020



V. BRØNDUM A/S

DK-8600 Silkeborg · www.broendum.com



When the service-alarm indicates that it is time to have the motor replaced – the vacuum cleaner / dust extractor must go to a workshop.

The top parts are removed – to allow the motor to be replaced.

Be careful not to squeeze or damage the wires.

Tightening torque : 4-6 Nm

For the reset of the service alarm the Ronda reset unit (item code 81.75.1028) must be used.

Following is done with all wires in place:

The Multi-fit connector for the pressure-switch and automatic is removed from the control-board.

Ronda reset unit is inserted in the connector on the control board, the machine is connected to 230V, and turned on - ON/OFF (red switch)

Wait 10 sec.

Turn off the machine – ON/OFF and remove (unplug) 230V.

Remove Ronda reset unit and connect the pressure switch and automatic connector to the control board.

Reassemble the machine – and test.

